



Figure 1: Silver plated copper time zero pull test - breaks at first ball bond.




Figure 2: Silver plated copper HTS (150 degrees Celsius)240hr pull test - breaks at first ball bond.






Figure 3: Silver plated copper 1xreflow pull test - breaks at first ball bond.




Figure 4: Silver plated copper 4xreflow pull test - breaks at first ball bond.